City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>7/8/2009</u>
Test to be performed:  Smoke Dyed Water X Dry ✓ Damp ☐ Wet ☐		Supervisor: <u>JAW</u>
Manhole_ID: S03AA1015MH	Test ID: <u>D1032-026023</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S05AA1002MH
0			Water Level	
183	12		Tap Factory	From 4004 Dorchester
183	10		Tap Factory	From 4004 Dorchester
183			Dye Test Visible	@ TF, 10oc - downspout
183			Manhole	S03AA1015MH
183			End of Survey	DYE TEST COMPLETED